


# Research and Development Technical Report ECOM-3576

CORROSION RESISTANCE OF ELECTRONIC PARTS

Charles P. Lascaro

May 1972




DISTRIBUTION STATEMENT

Approved for public release; distribution unlimited.



Reproduced by
NATIONAL TECHNICAL
INFORMATION SERVICE
ITS Department of Commerce

UNITED STATES ARMY ELECTRONICS COMMAND . FORT MONMOUTH, N.J.



# NOTICES

#### Disclaimers

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The citation of trade names and names of manufacturers in this report is not to be construed as official Government indersement or approval of commercial products or services referenced herein.

# Disposition

HINNING HINNING HINNING BEFER BEFER

Destroy this report when it is no longer needed. Do not return it to the originator.

# RESEARCH AND DEVELOPMENT TECHNICAL REPORT ECOM-3576

# CORROSION RESISTANCE OF ELECTRONIC PARTS

by

Charles P. Lascaro

Magnetics, Instrumentation & Interconnections Technical Area US Army Electronics Technology and Devices Laboratory

May 1972

DA Work Unit No. 1H6 62705 A057 01 141

Approved for public release; distribution unlimited

US ARMY ELECTRONICS COMMAND, FORT MONMOUTH, N. J. 07703

Unclassified			
Security Classification.			
DOCUMENT CONTI			constitution of the state of th
Security Classification of title, body of abstract and indexing a 1. ORIGINATING ACTIVITY (Corporate surface)	HADISHEN MUST SO	30. REPORT SE	CURITY CLASSIFICATION
U. S. Army Electronics Command		l	U
Fort Monmouth, New Jersey 07703		Sh. GROUP	
		<u> </u>	
3. REPORT TITLE			
Corrosion Resistance of Electronic Parts			
4. DESCRIPTIVE NOTES (Type of report and inclusive detec;			
Technical Report			
·			
Charles P. Lassaro			
6. REPORT DATE	76. 70TAL NO. 0	PASES	X. NO. OF REPS
May 1972	30	4 222027 1122	
M. CONTRACT ON GRANT NO.	at omelianon		-
a. PROJECT NO. 1H6 62705 £057	ECOM-3576	;	
- Task NoO1	SO. OTHER REPO	AT HOSE (Aug of	her numbers that may to contigned
a Work Unit No141		•	
10. DISTRIBUTION STATEMENT	ł		
Approved for public release; distribution of	inl <b>imite</b> d		
11. SUPPLEMENTARY NOTES	II. S. Ar		ics Comand.
	ATTN: AM		
	•	outh, New	<b>Jarsey</b> 07703
13. ABSTRACT	ł	*****	<del></del>
One of the design objectives of militate the degradation of humid tropical exposure bution to the failure mechanisms that can coratory humidity and salt fog acceleration of electronic parts in the Panamanian jung corrosion failure mechanisms are described by comparing laboratory exposed parts with life. Acceleration factors are then calculateen shore exposures and various salt-fog to show significant corrosion and fungus growide significant corrosion in two years tion factors of his field days per laborator acceleration factors of 36-h2.	s. Corrosicoccur. This tests with le and at ma and correla field resultated. Resultated. Parrosth in thr. Laborator	n provides study correctual field in shore actual field in with the store determine show gots exposed ree years, by humidity	a significant contri- relates various lab- ld exposure studies sites. Significant the field is provided mine field service cood correlation be- in the jungle begin while shore conditions tests have accelera-

DD . 1473 \*\* Unclassified \*\* Security Closelfication

A COLOR OF THE PROPERTY OF THE

Security Classification						
14.	LIN	K A	LIN	X b	FIN	t C
KEY WORDS	ROLE	WT	ROLE	WT	HOLE	WT
Corrosion			ĺ			
Electronic Parts			l		[	
Tropical Field Study						
Field Service Life					1	
Failure Mechanisms						
Accelerated Laboratory Testing		İ				
Salt Fog Testing					Į į	
Lead Wire Corrosion			!		<b>i</b> i	
Silver Higration						
Fungus Growth					[	
Maintenance Field Life					] [	
Long term Field effects					1	
Degradation of Electronic Parts						
Resistors						
Capacitors				ļ :		
Potentiometers	li		l i			
Inductors		i		} .		
Panama Field Studies						
Plastic Ercsion						
Field correlation with Laboratory Testing						
			ł			
			1 1			
		l i	İ			
					1	
				,		
,					i.	
•						•
	.				į	
	1					
			l i			
	,					
					Į i	
	) 1					
Į ·						
			l i			
	أسموسما			<u> </u>	L	

HISA-FM-1820-72

Unclassified

Security Classification

THE CONTRACTOR OF THE CONTRACT

П

# CONTENTS

•	Page
BACKGROUND	1
SUMMARY OF 1958 STUDY	1
SUMMARY OF 1968 STUDY	2
DATA PRESENTATION	3
DISCUSSION OF DATA	6
<ol> <li>Failure Mechanisms</li> <li>Tropical Field Service Life</li> <li>Maintenance Field Life</li> <li>Acceleration Factors</li> <li>Comparision of Studies</li> <li>Long Term Effects</li> </ol>	6 7 7 7 8 8
CONCLUSION	8
1. Failure Mechanisms 2. Tropical Field Service & Maintenance Life 3. Acceleration Factors 4. Long Term Degradative Effects	8 9 9
REFERENCES	9
ACKNOWLEDGEMENTS	10
FIGURES	
1. Summary of "Field Data" and "Acceleration Data" 2. X = Grey or tarnished plating 3. XX = Grey plus black spots 4. XXX = Grey with black and green spots 5. XXXX = Grey, black, green with necking 6. XXXX(F) = Corrosion with open leads 7. ESM = End Seal Migration 8. SM = Silver migration 9. CC = Case corrosion 10. PE = Plastic erosion 11. EC = Element Corrosion 12. ELC = Electrolytic Corrosion 13. FG = Fungus Growth 14. Seven Months Field Corrosion Data	11 12 13 14 14 15 16 17 18 19 20 21 22 23
15. Twenty-Four Month Field Corrosion Data	2/1

THE PROPERTY OF SECTION AND THE PROPERTY OF TH

5

A VICTO PERSON DE LE PRESENTATION DE LE PRESENTATION DE LE PRINCIPA DE LE PRINCIP

16.	Thirty-six Month Field Corrosion Data	25
17.	Lead Wire Corrosion at Jungle	26
_	Lead Wire Corrosion at Shore	26
19.	Number of Jungle Failures	27
	Number of Shore Failures	27
21.	Failure Mechanisme Observed in Four Accelerated Laboratory Tests	28
22.	Field Service Life for Jungle (J) or Shore (S) Exposure in Days	
	(Equivalent to 20 Days of Laboratory Tests)	29
23.	Laboratory Test Cycles Acceleration Factors	30

Control of Control of Control of the

#### BACKGROUND

One of the design objectives of military electronic equipments is to withstand the degradation of humid tropical exposures. Many study programs and tropical field experiences have shown that jungle and marine localities possess environments which produce corrosive failure mechanisms which contribute to electronic part and/or assembly failures. For many years, laboratory tests, such as the Moisture Resistance Test, Method 106 of MIL-STD-202, have been used to determine the resistance of applied protective designs, coatings, and finishes to tropical atmospheres. The moisture resistance test, however, was developed for use over twenty years ago and, at that time, it appeared suitable for designs and materials in usage. Since then, tropical field experience in Southeast Asia and improvement of parts, materials, and processes made possible the achievement of extended field service lives, maintenance cycles, and reliability performance which needed to be reflected in more effective and correlated laboratory test cycles. Many predicted service lives of parts or assemblies must be based upon known acceleration factors of laboratory testing. Recently, a fungus test per Method 508 and a salt-fog test per Method 509 of MIL-STD-810 were added to equipment specifications to assure increased fungus and corrosion resistance of parts, materials, and processes. The continued use of such tests, however, must be based upon their ability to predict field service life in short term accelerated laboratory exposure

and a management management of the contract of

Various studies have been made to expose selected electronic parts, such as resistors, capacitors, inductors, etc., to seashore and jungle sites at the Tropic Test Center, Panama Canal Zone, and to selected accelerated laboratory test cycles which included moderated salt-fog conditions. This report reviews the previous background data, and completes the analysis of the collated data, with special emphasis on the identity of the corrosion failure mechanisms that can occur for the purpose of providing a basis for a prediction of environmental reliability and service life capabilities of the parts, and correlation between the various accelerated laboratory test procedures performed. A special analysis is conducted of reduced salt-fog concentration test procedures.

#### SUMMARY OF 1958 STUDY

Initial efforts to correlate laboratory tests with tropical exposure had been conducted in 1958. Selected electronic parts had been exposed to jungle and seashore conditions at Galeta Point, Tropic Test Center, Panama Canal Zone, for periods up to eighteen months. Figure 1 shows a summary of the number of failures obtained for each type of part at each location. A comparision of the shore and shady jungle columns under the heading, "Field Results," shows a preponderance of failures occurring at the shore site, except for paper capacitors. Inasmuch as the average relative humidity is lower at the shore site due to the characteristics of this type of site, the larger number of failures could only be explained by an additional degradation factor which was salt vapour from the ocean.

Failure analysis of results in the field showed that lead wire corrosion was extensive with many open-lead wire failures occurring. End seal migration and case corrosion products were prevalent. Except for open-lead failures, corrosion was not a major factor in electronic failure rates that occurred.

As part of the study program, an attempt was made to duplicate these types of failures in the laboratory, using Method 106 of MIL-STD-202 and some modification thereof, including various adaptations of a salt spray test from ASTM B117-54T, with various percent salt solutions, as follows:

# Accelerated Laboratory Test Procedure Variations

- I 20 cycles, Method 106.
- 1, 3, 5, 7, 9, 11, 15, 17, 19 cycles of Method 106; 2, 4, 6, 8, 10, 12, 14, 16, 18, 20 of 20% Salt Spray.
- 20 each of a 22-hour Method 106 cycle; plus each cycle including 2 hours of 5% Salt Spray.
- 18 cycles, Method 106; and 5th and 15th cycles 2 hours of 5% Salt Spray included.
- V 15 cycles Method 106; and, 1st, 4th, 8th, 11th, and 16th cycles 5% Salt Spray.
- VI 20 each 24-hour cycles of: 22 hours Method 106, 2 hours 3% Salt Spray.

Column 1 of Fig. 1 shows that except for composition potentiometers, twenty cycles of Method 106 failed to reproduce field failure rates or types. Most of the variations of Method 106, plus a salt spray condition, provided accelerated factor rates beyond that produced in the field for each site. Variation IV appeared to be close to results obtained at the shore site in the field.

Predicted service life was 1400 days for a shady jungle site and acceleration factor for one temperature-humidity laboratory test cycle was 70, depending upon part design. Estimated acceleration factors of Test Variation IV over the bench site ranged from 10 to 130. A life of 200 to 2600 days was calculated for four parts exposed at the shore site.

# SUMMARY OF 1968 STUDY

In 1968, this work was continued on a newer family of subminiature parts.<sup>2</sup> Here again, eighteen selected parts were exposed at a jungle site and a seashore site for three years and these results compared to the following tests:

# Accelerated Laboratory Test Cycling

- 1. 20 days, Method 106B, MIL-STD-202, Humidity Test.
- 2. 20 days, 1% Salt-Feg at +60°C.
- 3. 20 days, steady swate Moisture Resistance at +90°C and 90% RH.
- 4. 20 days, 0.5% Salt-Fog at +50°C.

The units exposed in the field study were exposed with or without a polarizing potential. This potential is present in normal equipment operation and tends to accelerate certain corrosion processes. The absence of polarity simulates standby or storage conditions. The following parts were exposed:

Abbreviated Code	Type Part
CK	Ceramic Capacitor
CL	Fixed Tantalum Capacitor
CM	Mica Capacitor
CS	Solid Tantalum Capacitor
CT	Mylar Capacitor
MF	Metal Film Resistor
KC	Fixed Ceramic Capacitor
RC	Carbon Composition Resistor
RS	Variable Resistor
RL	Fixed Tin Oxide Resistor
RN	Film Resistor
RO	Fixed Carbon Resistor
RW	Wirewound Resistor
TA	Fixed Tantalum Capacitor
AC	Variable Ceramic Capacitor
VI	Inductor
VK	Fixed Ceramic Capacitor
WE	Fixed Inductor

For this report, only corrosion mechanism observations will be analyzed and compared with laboratory tests. Electrical data analysis will be continued and reported subsequently.

# DATA PRESENTATION

的,这种是一种,我们是这种,我们是是一种,我们是是一种,我们也是我们的,我们是是一种,我们是不是一种的,我们也会是一种,我们就是我们的,我们们就是我们的,我们们

THE ACTION WITH THE CONTROL CONTROL OF THE CONTROL

l. During periodic field trips to Panama, observations were made of the corroded condition of the parts. These observations were accomplished after periods of exposure of 7, 24, 36 menths. The data obtained at each of these times represent a time-related degradation level and, therefore, are eligible for use as a partial basis for rating each part's reliable service life capability in the field. Since these same parts were tested in the laboratory under two

humidity and two salt-fog tests, the data can also be used to estimate acceleration factors obtained for each test.

- 2. Based upon field observations and failure mechanism analysis, each corrosion failure mechanism obtained is hereby given, in addition to its contribution or significance to electronic part failure:
- a. Lead wire corrosion (LC): Lead wires are normally plated or tinned copper wires. A few are copper-clad steels. Principal constituents are usually tin-lead or tin over copper, nickel-tin-magnesium, copper-silver, or nickel-copper. Corrosive atmospheres first tarnish coatings or platings and progressively attack the basis lead wire metals via pin hole or anodic corrosion processes. It is reasonable therefore, to grade extent of corrosion by the following code:

Rating	M.	
0	No corrosion	
X	Grey or tarnished plating	Fig. 2
XX	Grey leads plus black spots	Fig. 3
XXX	Grey, black and/or green encrustation	Fig. 4
	Failure Level	
XXXX	Grey, black, green with necking	Fig. 5
(1) AAAA	Above corrosion with open leads	Fig. 6

经第二年,1980年

Inasmuch as the part assemblies are subject to shock and vibration in the field, potential failure could occur at the XXX level or higher.

b. End seal migration (ESM): Applied circuit voltage polarities can cause migration of corrosion products over insulating end seals with resultant loss of insulation resistance and increase of wettability during condensation. A previous report on this subject <sup>3</sup> established that lack of adequate filleting design of bushings (to prevent accumulation of contamination in inside corner designs) provided a corrosion failure mechanism which necked the leads adjacent to the part body and also deposited corrosion products over the surface of the insulated parts, thus shunting the resistance of the part (Fig. 7).

Parse menorable describerations and the contract of the contra

- c. <u>Solder corrosion (SC)</u>: Grey lead carbonate usually caused by residual flux contamination deposited by the part manufacturer. Lead-rich solder dips may also cause such corrosion products.
- d. <u>Silver migration (SM)</u>: Any silver platings or elements under conditions of direct current polarity and moisture will migrate through porcus or filled plastic insulation and eventually cause short-circuit failure. Silver migration is usually invisible until catastrophic short-circuit failure occurs (Fig. 8).
- e. <u>Case corrosion(CC)</u>: Metallic cases can corrode and contribute to migrating corrosion products. Since cases usually carry identification, corrosion may mean loss of part identification (Fig. 9).

- f. Plastic erosion (PE): Apparently, some plastic compositions are subject to chemical or fungus attack during tropical exposure. Salt exposures and voltage polarities accelerate this condition. Erosion may mean greying or dulling of surface with loss of identification, or deep erosions which bare part elements (Fig. 10).
- g. Element corrosion (EC): Moisture absorption through protective coatings may cause corrosion of metallic end caps, terminal connections, ferrite rusting, contact corrosion, stress corrosion, plating corrosion; these increase part resistance or contribute to reduced performance (Fig. 11).
- h. Electrolytic corresion (ELC): Such corresion may occur due to metallic couples of part elements within the part and can accelerate couple corresion and catastrophic failures as open or short circuits, depending on the type of mechanism (Fig. 12).
- i. Fungus growth (FG): The presence of fungus growth is considered a contributor of surface contaminants and corrosion electrolytes. The presence of fungus growth is also an indication that cleaning and maintenance of the assembly is due (Fig. 13).
- 3. The number of 18 part groups which exhibited significant occurrences of the above failure mechanisms after 7, 24, and 36-month exposures is shown in Fig. 14, 15, 16. Each test lot for each condition listed numbered 25. Figures 17, 18, 19, and 20 show the distribution of each failure mechanism with respect to location and exposure time. An indication of (F) beside any failure mechanism indicates that the part failed due to the mechanism alone.

Total post of the control of the con

4. The data and observations from the four accelerated laboratory tests are shown in Fig. 21. The calculation of equivalent field service life and acceleration factors are shown in Fig. 22 and 23. The data in Figure 22 shows the Equivalent Field Service Life, which each laboratory test cycle was capable of reproducing after 20 days of laboratory exposure. This was obtained by matching the terminal laboratory test result with each of three field test results at 10, 2h, and 36 months. The acceleration factors in Fig. 23 were obtained by dividing each equivalent service life time in Fig. 22 by 20, since each laboratory test was conducted for that period.

# DISCUSSION OF DATA

1. Failure Mechanisms: The failure mechanisms of electronic parts which were exposed in field tropical conditions and contributed to part degradation are as follows (listed in order of severity and showing the number of part groups which were susceptible):

	Jun	gle	She	ore	
	NP	P	NP	<u> </u>	Total
Lead Wire Corrosion	1	1	6	7	15
End Seal Migration	1	1	6	9	17
Plastic Erosion	2	2	4	4	12
Element Corrosion	2	3	3	4	12
Fungus Growth	8	6	4	5	23
Electrolytic Corrosion	2	3	3	4	12
Solder Corrosion	2	2	1	4	9
Silver Migration	1	2	0	2	5
Case Corrosion	1	1	1	1	4

The above numbers are the sum of each of 18 different type parts which exhibited failure mechanism effects as described to significantly affect electronic performance. All of these mechanisms were capable, in time, of contributing to catastrophic failures. Each of the above failure mechanisms could have been prevented by proper choice of materials and part design as follows:

The content of the co

Lead Wire Corrosion:	Use of two part pin-hole free plating of adequate thickness. Avoid couples, and poor filleting or end seal designs.
End Seal Migration:	Avoid or minimize corrosion of case or lead wire and right angle fillets design.
Plastic Erosion:	Use of inert and salt resistant plastics.
Element Corrosion:	Protect elements by adequate plating. Plastic coatings are not complete barriers to moisture entry.

Fungus Growth:

Protect part surface from outside contaminants. Periodic maintenance at every one to two years

may be necessary.

Electrolytic Corrosion:

Avoid excessive couples in part design.

Solder Corrosion:

Use approved fluxes, clean all residues, avoid

lead-rich baths.

Silver Migration:

Do not use silver electrodes in parts with filled or porous insulation where moisture may penetrate and direct current polarities may

occur.

Case Corrosion:

Provide adequate plating or coating protection

en e de le comparte de la comparte del la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la comparte de la compa

for any metallic case.

2. Tropical Field Service Life: The progression of corrosion effect on the parts studied indicate that part failures can be expected to become significant factors in the operation of equipment assemblies as follows:

Jungle: 3 years Shore: 2 years

- 3. Maintenance Field Life: To assure extended and continued service life in the field, maintenance is necessary to remove corrosion products and such contaminations as fungus growth. Maintenance periods should be selected to preclude the failures occurring in the next time period.
- 4. Acceleration Factors: By matching the results obtained in each laboratory test cycle and the corrosion results of parts exposed in the field, the following acceleration factors can be estimated:

Test		<u>Jungle</u>	Shore
Method 106, MIL-ST	D-202:	43.9	none
1% Salt Fog	:	not significant	41.5
0.5% Salt Fog	*	not significant	35.6
90°C Humidity	:	50.1	none

Because the 90°C humidity test provided a large number of catastrophic failures not obtained in field testing, this test should not be considered for accelerated testing. Its effectiveness, however, shows that temperature rate factors are profound and test temperatures should be raised as high as practical to increase degradation and acceleration factors. Method 106 provides no corrosion correlation with shore conditions and inversely, neither of the salt-fog tests provide correlation with jungle degradation factors. On this basis, neither test should be substituted for the other. The 0.5% Salt-Fog

test provides some desirable mitigation of severe corrosive effects. It may be possible that as the salt content is lowered further and with higher temperature use, a workable combination test may eventually be obtained. Lead necking, end seal migration, and plastic erosion failures require salt contamination to produce these failures.

5. Comparison of Studies: A comparison of the two studies reveals the following approximate data:

2000 01 1	Field Service Life (days)	Acceleration Factor (field days/TH day)
1958 Study Jungle Shore	11;00 200 - 2500	Method 106 = 70 TH SF Var. #IV = 10 - 130
1968 Study Jungle Shore	880 720 - 81 <del>;</del> 0	Method 106 = 14 TH SF Var: = 36 ~ 42

Considering the approximations made in reaching the above data, it is considered that the two studies corroborate one another.

6. Long Term Effects: Certain degradative processes require long-term exposure and, therefore, are not correlated by short-term tests. These are element corrosion, fungal growth, and silver migration. Corrosive processes are usually not severe in humidity tests unless salt and direct current voltage stresses are present. The appearance of even slight corrosion in laboratory humidity tests should be a basis for failing a part and requiring improved finishes.

### CONCLUSION

- 1. Failure Mechanisms: Electronic parts exposed to tropical environmental conditions are subject to failures because of the degradative influence of the following corrosion, erosion, and fungal effects:
  - a. Lead Wire Corresion
  - b. End Seal Migration of Corrosion Products
  - c. Plastic Erosion Due to Salt and Moisture Attack
  - d. Element Corrosion Due to Moisture Ingress
  - e. Fungal Growth and Surface and Plastic Degradation
  - f. Electrolytic Corrosion Due to Galvanic Couples in the Parts
  - g. Solder Corrosion Due to Flux Contaminants
  - h. Silver Rigration Due to Use of Silver and Porous or Filled Plastic Insulation
  - i. Case Corrogion Due to Poor Finishes

Preventative techniques are recommended within this report and other referenced literature<sup>5</sup> and most are within current state-of-the-art techniques. The

field service life and maintenance time recommended below are applicable to parts used in louvered cases open to outside contaminations. Protection by containing the assembly in sealed cases capable of maintaining dry clean internal conditions would extend service lives and minimize maintenance factors considerably.

2. Tropical Field Service and Maintenance Life: Terminal degradative corrosion effects can be expected during the following exposure periods. Maintenance procedures are recommended prior to irreversible corrosion or fungal growth effects:

Jungle Field Service Life

Jungle 3 years

Shore 2 years

- 3. Acceleration Factors: Laboratory test conditions provide the acceleration shown in Paragraph 5 of Discussion of Data above. Method 105 provides no correlation with serious corrosive effects obtained at the shore or marine conditions. Salt-fog tests do provide correlation and significant acceleration. High temperature, high humidity tests are harsh and do not correlate well with field conditions. Salt fog testing is necessary for electronic assemblies, if corrosion prevention is required in tropical environments.
- 4. Long Term Degradative Effects: Accelerated laboratory testing, in periods of ten to twenty days, do not reproduce long-term failure types, such as element corrosion, fungal growth, silver migration, and severe lead wire corresion with necking and/or open circuits.

obolivataa etalutuutiiseksisalivulkat ohteitalasekaskaskaskaskasia tenaletsiiseksisteksisisteksi

### REFERENCES

- Easterday, J. L., A. E. Mace, and W. D. Chapin, "Laboratory Test Procedures for Predicting the Tropical Service Life of Electronic Components and Materials," 1958, Final Report, Battelle Memorial Institute, Columbus, Ohio, Contract DA-36-039-SC-66518.
- 2. Dennison, B. H., "Tropical Service Life of Electronic Parts and Materials," 1968, Melpar, Inc., Falls Church, Virginia, Final Report, Contract DA28-043-AMC-02222(E).
- Lascaro, C. R., "Corrosion Resistance of Electronic Parts in Tropical Environments," November 1967, US Army Electronics Command, and B. H. Dennison, Melpar, Inc., presented at 50th Anniversary Conference on Corrosion of Military and Aerospace Equipment, Conver, Colorado.
- h. Chaikin, S. W., "Study of Effects and Control of Surface Contaminants on Dielectric Materials," January 1958, Stanford Research Institute, Final Report, Contract D4-36-039-SC-6hh5h.

5. Lascaro, C. P., "Design of Tropical Resistant Electronic Equipment," June 1970, IEEE Transactions on Parts, Materials and Packaging.

# **ACKNOWLEDGEMENTS**

The author acknowledges the assistance of the following:

Mr. Erik Linden, US Army Electronics Technology & Devices Laboratory, for implementing many field test arrangements in Panama and at the Hexagon laboratories.

Mr. A. J. Raffalovich, US Army Electronics Technology & Devices Laboratory, for assisting in corrosion analysis studies.

Massrs. A. Fini and B. Dennison of Melpar, Inc., for assistance in field studies.

Mr. Frank T. Brannon, scientist in charge of the field stations, and Mr. Anthony Gressel, Engineering Technician, for performing field measurements; both of Tropic Test Center, USATECOM, Panama Canal Zone.

Dr. C. R. Southwell, Scientist in charge, Naval Corrosion Test Laboratory, NRL, Panama Canal Zone, for technical assistance in the field.

THE CONTROL OF THE CO

•	C									
			Field	Field Results		Accelerati	Acceleration Laboratory Test Results	ry Test Re	sults	
	Part	Shore	Shady Jungle	Open Jungle	н	II	III	VI.	Α	l l
	Resistor, Composition	3/10*	01/0	0/10	0/10	0/50	0/50	1/20	0/20	
	Resistor, Boro-Carbon	2/10	1/10	2/10	01/0	20/20	20/20	TO/20	10/20	10/50
	Capacitor, Paper	2/50	12/20	0/50	0/50	10/20	7/20	3/20	2/50	
11	Capacitor, Glass	14/20	2/20	3/20	0/50	17/20	20/20	16/20	20/22	
	Potentiometer, Composition	7/20	5/20	1/20	9/20				, to magnifica	

Data Legend A = Number Failures, B = Number Tested

Data taken from Final Summary Report, Contract DA36-039-56-645,8, "Laboratory Test Procedures for Predicting the Tropical Service Life of Electronic Components and Materials."

Fig. 1. - Summary of "Field Data" and "Acceleration Data"

W. Character and the antition of the antition

ء شر






Figure 2  $X = (\cdot, y)$  or tarnished plating

NA STATES OF THE



n de de le composition de la composition della composition de la composition de la composition della c



The construction of the co

RN60C

FINCOC

(シ)××××




Figure 7
ESM = End Ceal Migration

Figure 8

SM = Silver migration





Figure 9

CC = Case corrosion




# RESISTOR, CARBON FILM, BERN, ELECTROLYTIC EROSION OF LEAD TERMINAL AND PROTECTIVE PLASTIC

Figure 10 State of State of PE = P. astic erision



ALINES CHECK CONSTRUCTOR CONTINUES C



right ...
ELC = Electrolytic . real n




Figure 13

Figure 13

Figure 13

FG = Fungus Growth

AN STATES OF THE SECTION OF THE SECTION OF SECTION SECTIONS OF THE SECTION OF THE

Part		Tropical	Field	
	Jun	gle	Sho	
	Non-Polar	Polar	Non-Polar	Polar
CK	0	0	x	ХХ
CL	0		X	
CM	0	o ¦	Х	XX
CS	C	0	X	XX
CT	0		Х	X
MF	0	0 0	X	XX
KC	0	0	Х	X
RC	0	0	XX	XXX
RS	0	0	0	0
RL	0		Х	XX
RN	0	0	Х	XXX
RO	Ç		Х	X
RW	0	0	X, EC	XXX, EC
TA	0		X	XX
AC	0		0	0
VI	0	ļ	0	Х
VΚ	5		0	0
WE	0	e	Х	XX

The car of also and the control of t

Fig. 14 - Seven Months Field Corrosion Data.\*

<sup>\*</sup>Failure Mechanism Code Explained in "Date Presentation," Par. 2.

Part	Tropical Field				
	Jun	gle	Shore		
	Non-Polar	Polar	Non-Polar	Polar	
CK	X	X	X	XXXX(F)	
CL	X, CC, ESM	X, CC, ESM	XX, ESM, CC	XX, ESM, CC	
CM	0	0	XX, ESM	XX, ESM	
cs	x	x	X, PE	XX, SC, PE	
CT	0	0	XX	XXX, ESM	
MF	x	x	XX, ESM	XXX, ESM	
KC	0	0	ХХ	хх	
RC	0	0	XX, SC, ESM	XXX, SC, ESM	
RS	0	0	0	0	
RL	0	0	XX	xxx	
RN	0	0	XX, SC	XX, SC, ESM	
RO	0	0	XX, ESM	XX, ESM	
RW	0	0	X, EC	XX, EC, SC, PE	
TA	0	0	XX	XXX	
VC	0	· 0	X, PE	X, PE, ESM	
VI	0	0	X, PE	XX, PE	
VK	0	0	X	х	
WE	0	0	X, ESM	XX, ESM	

The contraction and definitions and an accordance of the contraction o

\*Failure Mechanism Code Explained in "Data Presentation," Par. 2.

Fig. 15 - Twenty-Four Month Field Corrosion Data\*

Part	Tropical Field				
	Jungle			hore	
	Non-Polar	Polar	Non-Polar	Polar	
CK	xxx	XXX	XXXX, PE	XXXX(F), PE	
CL	o, FG, CC	o, FG, CC	XX, ESM, CC	XX, ESM, CC	
CM	X, FG	X, FG, SM(F)	XX, FG	XX, ESM, SM(F), FG	
cs	X, FG	X	XX, EC(F)	XX, ESM, SC(F)	
CT	О	0	XX, PE, ESM	XXX, EX(F)	
MF	X, FG	XX	ХХ	XX, ESM, PE	
KC	0, PE	O, PE	XXX, ESM, SC	xx	
RC	хх	XX, EC	FG, SC	XXXX, SC, ESM	
RS	0	0	· х, ре	FG, EC	
RL	o	х	XXX, ELC	XX, PE, ESM(F), ELC	
RN	X, SC, FG	X, SC, FG	XX, ESM	XXXX(F), EC(F)	
RO	FG	0	XXX, ESM	XX, ESM	
RW	0	0	XXX, FG	XXX, EC	
TA	O, FG	O, FG	SC, FG	XXXX, FG	
VC	SC, SM, FG	SC, SM, FG	FR, PE, FG	SM(F), SC, FG, EC	
VI	EC, PE	0	ХХ	EX, CC, FG, PE	
VK	0	o	XX	xx	
WE	X, FG	XX, FG	XXX, ESM	XXXX, ESM, SC	

Fig. 16 - Thirty-six Month Field Corrosion Data\*

<sup>\*</sup>Failure Mechanism Code Explained in "Data Presentation," Par. 2.

Exposure time	7 months	24 months	36 months
Mechanisms Lead Corrosion (LC)	Number of Pa	rt Groups Havin	g Failures
0 X XX XXX	18 0 0 0 0	14 4 0 0	8 4 4 1
XXXX XXXX(F)	- Failure Level -	0	0

Fig. 17 - Lead Wire Corrosion at Jungle\*

The article principal the experiment of the properties of the prop

Exposure time	7 months	24 months	36 months
Mechanisms Lead Corrosion (LC)	Number of Pa	rt Groups Havi	ng Failures
0 X XX XXX	3 4 7 3 - Failure Level -	14 4 9 6	0 1 8 5
XXXX XXXX(F)	0 0	0	3

Fig. 18 - Lead Wire Corresion at Shore

<sup>\*</sup>The above data shows that significant lead wire failures do not occur until after three years in the jungle and after two years at the shore.

Exposure Time	- 7 months	24 months	36 months
Failure Mechanism	Number of Part	Groups with	Failures at Jungle
ESM	0	1	0
SC	0	0	2
SM	0	0	2
cc	0	1	1
PE	0	0	.2
EC	0	0	3
ELC	0	0	0
FG	0	0	6

Fig. 19 - Number of Jungle Failures

The state of the s

Exposure	Time	7 months	24 months	36 months
Part	]	Number of	Part Groups wit	h Failures at Shore
ESM		0	9	9
SC		0	4	14
SM(F)		0	0	2
CS		O	1	1
PE		С	L	Ц
EC		1	1	4
ELC		0	0	1
FG		0	0	5

Fig. 20 - Number of Shore Failures

Part	Humidity Pest Cycle 136	Salt Fog Test 60°C, 1% SF	Salt Fog Test 50°C, 0.5% SF	Humidity Test 90°C, 100% RH
C <b>K</b>		LC(F), PE	LC	LC
CL	LC, ESM	0	LC, CC	LC, CC
CM		LC, SM	0	PS
CS	İ	LC(F), PE, EC	LC, PS, EC	PS, SC
CT		0	LC	0
MF	LC	LC(F), ESM	LC	LC, PS
KC	0	LG(F), ESM	LC	0
RC		LC, ESM	-	C
RS	0	LC, ESM	ļ	
RL	0	LC, ESM, Str Cr	L	
RN		LC(F), PE	LC, SC	LC, EC
RO	LC	LC, ESM	LC, ESM	0
RW		LC, ESM, EC	rc	
TA	LC	LC	LC	EC
VC	CC, ESM	SM, EC		
VI	EC	LC(F), EC	LC, EC	SC, EC
VK WE	0	LC, SM	LC SC	LC, EC

Control control of the control of th

# Legend:

0 = No failure mechanisms observed
Blank space = part was not tested
Str Cr = Stress Corrosion (not listed in text)
PS = Plastic Swelling

Fig. 21 - Failure Mechanisms Observed in Four Accelerated Laboratory Tests

Part	Part Laboratory Test Cycle				
	Method 106 HT	x 1% SF	0.5% SF	90°C, HT	
CK		S 720	S 720	J 1080	
CL	J 720	s 300	S 720	J 720	
CM		S 1080 .	S 300	J 1080	
CS		s 1080	S 1080	J 1080	
CT		S 300	S720	J 1080	
MF	J 1080	S 720	S 720	J 1080	
KC	J 720	S 1080	S 720	J 720	
RC		S 720		J 720	
RS	J 1080+	S 1080			
RL	J 720	S 720	S 720		
RN		S 1080	S 720	J 1680	
RO	J 1080+	S 1080	S 720	J 1080	
RW		S. 1080	\$ 300		
TA	J 1080+	S 720	S 720	J 1080	
VC	J 1080	S 720			
VI	J 1080	S 1080	S 720	J 1080	
VK	J 720	s 1080	S 1080	J 1080	
WE	J 300	s 300	S 720	J 1080	

policina de la composition della ### NOTES:

The second of th

- 1. Jungle Data was compared to huridity tests (J)
- 2: Shore Data was compared to Salt Fog tests (S)
- 3. SF = Salt Fog
- 4. HT = Humidity Test

Fig. 22 - Field Service Life for Jungle (J) or Shore (S) Exposure in Days (Equivalent to 20 Days of Laboratory Tests)

(Equivalent Field Service Life / 20 Laboratory Test Cycles)

Part	106, MRT	1 <b>%</b> SF	0.5% SF	90°C MRT
CK		s 36	s 36	J 54
CL	J 36	S 15	s 36	J 36
CM		S 54	S 15	J 54
CS		S 54	S 54	J 54
CT		S 15	S 36	J 54
MF	J 54	S 36	S 36	J 54
KC	J 36	S 54	S 36	J 36
RC		s 36		J 36
RS	J 54+	S 54		
RI.	j 36	s 36	S 36	
RN		S 54	S 36	J 54
RO	J 54+	S 54	S 36	J 54
RW [		S 54	S 15	
TÂ	J 54+	s 35	S 36	J 54
<b>VC</b>	J 54	s 36		
VI	J 54	S 54	S 36	J 54
VK	J 36	S 54	S 54	J 54
WE	J 15	S 15	s 36	J 54
Avg	43.9	<b>41.</b> 5	35.6	50.1

Reported by Antibulation of the second of th

\*Acceleration Factor = Field Days per one lab day
Fig. 23 - Laboratory Test Cycles Acceleration Factors\*